


Skaneateles Lake Water Service Illustration

Illustration is not to scale



WATER SAMPLE TEST RESULTS, 2025

SAMPLE LOCATION AND DATE	7-7	7-14	7-21	7-28	8-4														
1 Skaneateles Gatehouse-Intake 1	ND	ND	ND	ND	ND														
2 Skaneateles Gatehouse-Intake 2	ND	ND	ND	ND	ND														
3 Clear Well 1/2 at Gatehouse	-	-	-	-	-														
4 Clear Well 3 at Gatehouse	-	-	-	-	-														
5 Skaneateles UV Plant	-	-	-	-	-														
6 Elbridge UV Plant	-	-	-	-	-														
7 Westcott Incoming	-	-	-	-	-														
8 Westcott Outgoing to Syracuse	-	-	-	-	-														
9 Woodland Incoming	-	-	-	-	-														
10 Woodland Outgoing to Syracuse	-	-	-	-	-														
11 Skaneateles HS	-	-	-	-	-														
12 Byrne Dairy	-	-	-	-	-														
13 Elbridge-North	-	-	-	-	-														
14 Jordan Town Hall	-	-	-	-	-														
15 Syracuse-Burnet & Thompson	-	-	-	-	-														

Values in parts per billion (ppb)
ND = Non Detect, equals less than the required method reporting limit of 0.3 µg/l
"- " = Not Sampled